









# **Annex 7**


## **Multiple use of water**














**CROP EVAPO-TRANSPIRATION**  
8600 ha - 630mm/season  
(Pan Evap.)










**ISSUES FROM THE MAIN RESERVOIR**






**OUTFLOWS KIRINDI OYA  
(River)**










**IRRIGATION MODERNISATION  
FRANCE - CABANNES 13 1980**

**Surface system**  
**groundwater overuse**  
**need for modernization**



## CONCLUSION (1981)

**Surface irrigation maintained in upstream part to allow groundwater recharge**

**Modernization in downstream part with drip irrigation supplied by pumping from groundwater**

